



*FAA Centers of Excellence
3rd Joint Annual Meeting
2003*

DC-9 Tee Cap Inspection

**Christopher Smith
FAA TC**

&



**Igor Komsky
Northwestern University**






Importance of the T-cap inspection

DC-9's T-cap is a structural member that redistributes load from the wing skin and stringers to the wing box



560 DC-9s that required inspection



The originally-installed T-caps were fabricated from 70-75T6 aluminum and were prone to exfoliation corrosion and stress corrosion cracking






Why the new inspection method was needed?

Service Bulletin 57-98:

Gain access to the center wing tank by removal of access panels, purging of the tanks, removal of barrel nuts.



Perform visual inspection of the area between and under the stringers.

Reassemble the aircraft.



800 man-hours without repair





Alternate inspection method – ultrasonic scanning from the aircraft skin without disassembling of the aircraft

48 man-hours without repair



Ultrasonic probes

New concept:

Ultrasonic inspection of the multi-layered aircraft structures through the sealant layers from the aircraft skin






Ultrasonic images of cracks and corrosion




Cost savings-
about \$9,000 per aircraft
An additional savings of
\$20,000 per day
is achieved due to the
reduction in
maintenance downtime
(NTIAC)




Spotface 7% & 4%

Exfoliation corrosion
7%, 5%, & 10%



Stress corrosion cracks
In the vertical flange



Spotface 7% loss


Exfoliation corrosion 7% loss

Spotface 4% loss






Key to a successful technology transfer






Applications of the new inspection technology





Applications of the new inspection technology


DC-10 spar-cap/strap connection




Ultrasonic scanning system

Bill Jappe
(Boeing, Long Beach)
inspects DC-10
at Northwest Airlines



**Revision of the DC-10
SID NDI Manual was
issued in October 1997**





Dual-beam ultrasonic transducers

Boeing 777
side of body splice



Crack detection in
the T-chord/Paddle fitting
interface of the Boeing 777
side of body splice.

Dual-beam
ultrasonic transducers







Applications of the new inspection technology









C-141: Ultrasonic inspection of the fastener holes in the spanwise splice joints (inspection performed by SAIC/UII)




Ultrasonic inspection of the F-15 lower wing spar from the wing skin




Fatigue crack




Ultrasonic A-scans from the fatigue crack and EDM notches



Ultrasonic inspection of the KC-10 lower-wing/fuel-cell structure



Eddy current inspection - 9,000 man-hours
Ultrasonic inspection - 400 man-hours (SAIC)







Applications of the new inspection technology



Ultrasonic inspection of Fairchild SA226/227




Field tests at Superior Aviation, Iron Mountain, MI






Applications of the new inspection technology

Cessna Citation 7 wing structure



Unassembled Citation 7 wing structure with B-scan images of the fastener holes with long cracks in the second layer. Inspection has been conducted from the top layer (wing skin).



Unassembled Citation 7 wing structure with B-scan images of the fastener holes with short cracks in the second layer. Inspection has been conducted from the top layer (wing skin).






Applications of the new inspection technology




Commercial inspection systems


**MAUS IV
Boeing**



**Ultrasonic imaging of
the second layer cracks
with concurrent sealant
monitoring**



**ScanMaster
IRT**







What is next?



Boeing 747 NDT

Rear Spar Upper Chord	SID 57-10-09
Rear Spar Lower Chord Horizontal Flange	SID 57-10-08
Front Spar Lower Chord Horizontal Flange	SID 57-10-17
Front Spar Upper Chord Horizontal Flange	SID 57-10-20
Center Section Midspar Lower Chord	SID 57-10-21
Wing Midspar Lower Chord – WS 586.0 to WS 862.0	SID 57-10-23
Wing Midspar Lower chord Inboard Nacelle	SID 57-10-24
Wing Center section Lower Skin Splice Stringers S-5C and S-15C	SID 57-10-26
Wing Upper Midspar Chord	SID 57-10-27
Wing Center Section Upper Aft Skin at BBL 0.00	SID 57-10-28
Wing Rib Upper Chord Horizontal Flange at Side-of-Body Splice	SID 57-10-29
Inboard Nacelle and stringers S-5 and S-15	SID 57-10-32
Internal Splice Plate	SID 57-10-33
Mid-spar splice	SID 57-10-34



Boeing 757 NDT

Rear Spar Lower Chord	SID 57-10-01
Lower Chord	SID 57-10-02
Lower Splice Stringer	SID 57-23-01




Boeing 767 NDT

Stringers at WS 694.2 to WS 344.3	SID 57-20-01
Splice Stringer at WS 694.2 to WS 344.3	SID 57-20-02
Wing-Lower Chord	SID 57-20-03
Rear Spar Lower Chord	SID 57-20-04

Boeing 777 NDT

Side of Body Joint	SID ???
--------------------	---------



American Airlines



FedEx

Airbus 300-600






What is next?




Conventional one signal technique



Dual-signal technique



Ultrasonic crack sizing using dry-coupled transducer modules





Any more challenges?

